SWL Group of Companies

SWL Rope Lifting & Testing Ltd Lloyds Beal Site Services Ltd Lloyds Ship Safety Services Ltd SWL NDT Ltd SWP Compressed Air Services Ltd



Head Office

Unit 4 Monza House Third Avenue, Millbrook, Southampton, Hampshire, SO15 0LD www.swl.org.uk

REPORT OF THOROUGH EXAMINATION OF WORK EQUIPMENT

Provision and Use of Work Equipment Regulations 1998 (PUWER)

Date of Thorough Examination: 22/08/2025	Your Reference:		Report #: 599414	Colour Code: N/	Ά	Job No: 03-19406			
Name and Address of employer for whom the thorough examination was Address of premises at which the examination was made:									
made: Premier Group UK - SapphireAv Unit 8-9 Wern Industrial Estate, NP10 9FQ		Unit 8-9	Premier Group UK - SapphireAv Unit 8-9 Wern Industrial Estate NP10 9FQ						
Description and identification of the equipment: Description: Fall Arrest System - 5MTRs Serial number: SK-5 Asset number: N/A		Safe V	Vorking Load(s): 135 Kg	Date of manuf known		Date of last thorough examination: N/A			
	Yes No	Was t	he examinatior	n carried out:					
Is this the first examination after installation or assembly at a new site or location? If the answer to the above question is YES has the equipment been installed correctly?			Within an interval of 6 months? Within an interval of 12 months? In accordance with an examination scheme? After the occurence of exceptional circumstances?			Yes No ✓ ✓ ✓ ✓			
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect (If none state NONE):									
NONE									
Is the above a defect which is of immediate dang	jer to persons?				YES		NO	✓	
Is the above a defect which is not yet but could become a danger to persons (if YES state the date by when)									
Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE									
Identification of any parts not accessible for examination:									
NONE									
Particulars of any tests carried out as part of the examination: (If none state NONE):									
Carried out destruction test on customers fall arrest system. First Defect: Carabiner broken at 360 Kg (We fitted new carabiner to wire rope to test limit of the block) Second Defect: Wire rope snapped at 675 Kg									
Observations made during examination:									
report with qualification:			atest date by which next thorough examination must be carried out: 9/08/2025						
M. Lomos									